

FMP-10 & FMS-10 MPO Tester

Manual

Please read this guide before use



Specification

FMP-10 & FMS-10	
FMS-10 MPO Light Source	
Optical Interface	12 cores MPO port (female)
Wavelength	850nm
Spectral type	VCSEL
Channel	12
Data Interface	USB
Wavelength Recognition	Reserved
Modulation	CW(Low/High Power mode)、270Hz、1kHz、2kHz
FMP-10 MPO Power Meter	
Sensor	InGaAs
Optical Interface	12 cores MPO port (female)
Calibrated Wavelength	850nm, 1300nm, 1310nm, 1550nm
Channel	12
Test Range	-60dBm~+3dBm
Resolution	±0.01dB
Uncertainty	±0.5dB
Maximum input power	+13dBm
Unit	dBm/dB(REF)
Threshold Setting	4 wavelength
Reference Setting	4 wavelength
Data storage	300sets
Data interface	USB
Wavelength Recognition	Yes
Polarity Test	According to TIA-568-C.0
Frequence Recognition	270Hz、1kHz、2kHz
General	
Display	TFT-LCD
Auto Power-Off	Yes
Power Supply	NiMH batteries /AC adapter
Working Hours	≥10 hours
Working Temp	0°C~50°C
Humidity	0~95% (non condensing)
Dimension	190L×105W×55H mm
Weight	About 700g



Safety Instructions

Warning



To avoid the risk of injury or death, always observe the following precautions before initializing the unit:

- To prevent hazardous radiation exposure, use only the controls or adjustments and perform only procedures specified for the laser source.
- If using a voltage-reducing autotransformer to power the unit,ensure that the common terminal connects to the earthed pole of the power source
- > Use only the type of power cord supplied with the unit.
- > Willfully interrupting the protective earth connection is prohibited.
- Never look into the end of an optical cable connected to an optical output device that is operating.Laser radiation is invisible,and direct exposure can severely injure the human eye..for more information,see the user's manual of the laser source in use.
- > Do not use the unit outdoors.
- To prevent potential fire or shock hazard,do not expose the unit to any source of excessive moisture.
- > Do not operate the unit outdoors
- Do not interrupt the protective earth grounding. Any such action can lead to a potential shock hazard that can result in serious personal injury
- To prevent potential fire or shock hazard,do not expose the unit to any source of excessive moisture.
- Unless absolutely necessary,do not attempt to adjust or perform any maintenance or repair procedure when the unit is open ed and connected to a power source.
- > Repairs are to be carried out only by a qualified technician.
- Do not attempt any adjustment, maintenance, or repair procedure to the unit's internal mechanism if immediate first aid is not accessible
- Disconnect the power cord from the unit before adding or removing any components.
- Operationg the unit in the presence of flammable gases or fumes is extremely hazardous
- Do not perform any operating or maintenance procedure that is not described in the user's manual



Standard Configuration

FMP-10 & FMS-10 tester、power adapter、Standard MPO jumper。※All changes with standard accessary and optional accessary price are subject to change without notice



	Num	Items	Description
	Front P	anel	
6	1	Power switch	Long Press: Power ON/OFF the meter
	2	TWIN switch	Reserved,
	3	Modulation Switch	Long Press: Save current power value Short Press: Select modulation mode(CW/270Hz/1KHz/2KHz)。
	4	Test Switch	Start/r stop a test
	5	Navigation Panel	 Select certain channel Switch between high/low power by "ok" button
35	6	MPO Port	
	Back Pa	inel	
	7	12VDC Port	
	8	USB Port	
	9	Battery compartment	Contain 4*AA batteries
9 (9)			




	Num	Icon	Description
Front Panel			
®	1	Power Switch	Long press: Switch on/off meter
	2	Unit Switch	Short Press: Switch power wavelength Long Press: Zeroing current power value
	3	Save button	Save current power value
	4	Menu Switch	Switch to main menu or last menu
	5	Navigati on Panel	
	6	MPO Port	
	Back Pa	anel	
	7	USB Port	
CAUTON CAUTON	8	12VDC Adapter port	
	9	Battery compart ment	Contain 4*AA batteries
3			




2.Interface

2.1 FML-10





2.2 FMP-10



Current Wavelength



3. Application

Caution	
	For accurate measurement please preheat the equipment no less than 15 minutes.

Warning	
	Don't direct the optical port to human eyes, laser may cause permanently damage !

3.1 FMP-10

3.1 1Measurement

FMP-10 could display maximum 12channel power value, showed as follow figures:

Zeroing: Long press"Unit"button to set zero for all the channels. **Unit switch**:short press"Unit"button to switch unit between "dB" and "dBm

If power value shows "high" or "low" that mean value is out of the range

MPO	D POW	ER MI	ETER
СН	dBm	СН	dBm
1	low	7	low
2	low	8	low
3	low	9	low
4	low	10	low
5	low	11	low
6	low	12	low
λ: 850	nm	F	ile:011







3.2 Setting

FMP-10 has ten menu items, showed as follow:

•	1、	Wavelength	Set wavelength
---	----	------------	----------------

- ◆ 2 、 Threshold Set Threshold
- ◆ 3 、 Reference Set Reference value
- ♦ 4 、 Calibration
 Set Calibration value
- ◆ 5 、 File File management
- ♦ 6 、 Back light Adjust backlight
- ◆ 7 、 About Check detail information of this meter






Figure 3

♦ Wavelength

User could choose 850nm, 1300nm, 1310nm, 1550nm measuring wavelength.




Figure 4

♦ Threshold

Set threshold for current test ,this setting will help user to quick judge whether channel is meet the requirement.

Polarity: A	
Threshold	1
ILmax:	<u>2</u> .00 dB
MENU:Esc	OK:Enter

Figure 5



• Reference

Set reference value for current test.when use "dB" as unit, user should set reference value:

$P_D = P_R - REF$

P_D=Display power P_R= Real power REF=Reference value




Figure 5

Calibration

Set calibration value for the meter




Figure 6

♦ File

User could check or delete the history files in this interface






Figure 7

Back light

Adjust backlight in this interface




Figure 8



4.Q&A

Fault	Analyze	Slove
Test is not accurate	Connect port with a clean jumper and power meter, check whether measurement is accurate	Unload optical adapter,clean it and fiber terminal by swab,then check Power value. Lightly clean the sensor of power meter by swab,check Power value.
Blurred	Spots on the display, figure is not	Restart,get away from the
screen	clear.	magnetic field.
Crash	Display not refresh.	Restart.



5.Maintenance

	Unproper or polluted fiber and instructment may damage the port of device.
Caution	Don't push connector hard, the ferrule of connector is fragile.
\wedge	 Clean connector by alcohol and dust-free paper before test
	Cover the dust cap for tester every time after turn off, if there is a jumper connect to the tester we suggest not
	removeing it so as to reduce connection times